

Global Energy Consulting, Inc.  
11171 Cherry Hill Dr.  
North Tustin, CA 92705

January 15, 2016

Mr. Joshua Cwikla  
320 W. Fourth St.  
Suite 200  
Los Angeles, CA 90013

Re: Order No. R4-2015-0412& Garner Engineering J-1 Production Facility

Dear Mr. Cwikla:

The relative short notice of Order No. R4-2015-0412 coupled with our extremely low water production rate has not allowed us to collect adequate fluid samples for testing. We respectfully ask for an additional thirty (30) days to respond. This would allow time for water accumulation and a period for the extensive laboratory testing.

The order, dated December 18, did not reach our office until January 9. During, and as a part of our normal operations, the sump fluid was taken for disposal on January 7. This left us with no water for sample collection. Additionally, our water production rate is only gallons per day, and we must produce over 600 gallons before any is any fluid (a) transferred to the sump, and (b) accessible for sampling.

Along with our volume restrictions, the considerable amount of testing that needs to be completed will take no small amount of time to produce results.

I appreciate your consideration in this matter, and will look forward to your ruling.

Sincerely,

Drew Riley  
Global Energy Consulting, Inc.  
562.481.5008  
[driley@scenergyservices.com](mailto:driley@scenergyservices.com)